

Has shaft now examined/fitted a continuous liner?

Approved oil gland?

COPY

Ship's name

YELKENCI

Port

137

No.

5325

Class is subject to

— MIL

Last survey date

3/4/63

17153 due 2/63 now commenced.
SPS due 7/63 now held
Some repairs effected

**It is submitted that the
vessel WILL BE eligible
for the record MBS 4/63
when the survey has been
completed.**

and record SPS 4/63 now

To complete 17153 —

Safety valves of Centre and Starboard boilers to be adjusted
under steam



© 2021

Lloyd's Register
Foundation

011397-011407-0345

End. E.2

Minute

Deferred for comp. MBS

HEADER