

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME m.s "ADRI V111"

REPORT

Dja.

5669

VC The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This ship was built at Hong Kong (12.58) for service in the Indonesian Archipelago and the class *100A1 "Indonesian Archipelago Service" recommended WHEN a report has been received of its satisfactory condition on arrival within its service area.

For further particulars see Endorsement dated 23.1.59.

The Djakarta Surveyor reports (9.59) ship generally examined afloat and in drydock and found in satisfactory condition.

IT IS FURTHER SUBMITTED the ship is now eligible to be classed *100A1 "Indonesian Archipelago Service" as previously recommended with record of DS. 9.59.

*100 A1 "Indonesian Archipelago Service"
DS. 9.59.

Particulars for R.B. as per Endorsement dated 23.1.59.

IN S.R.L. APPENDIX.

(Bottom plating to be examined internally annually (cement omitted))

✓
R.S.G.

6. 11. 59.



© 2021

Lloyd's Register
Foundation