

Condition of Class.

NAME OF VESSEL... "GENERTON"

Extract from Freeboard Verification of marking form received
from..... Sunderland Surveyors dated... 15.12.36.

Moulded depth	26	ft. 7 ins.
Corresponding draught	24	ft. $2\frac{1}{4}$ ins.
Moulded depth as shewn on draught sheet	26	ft. 7 ins.
Tropical freeboard	2	ft. $1\frac{3}{4}$ ins.
Summer "	2	ft. $7\frac{3}{4}$ ins.
Winter "	3	ft. $1\frac{3}{4}$ ins.
Winter North Atlantic freeboard	-	ft. - ins.
Fresh water allowance	$6\frac{3}{4}$	ins.

Marked from ~~wood~~/steel upper deck.

Checked by... *hmm*

Date... 18.12.36...



© 2021

Lloyd's Register
Foundation

011912-011926-0194