

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

Steel S.S. "Briarpark."

Report

Gls.

No. 42664.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

When due _____

✱ 100.A.1. (Steel)

18k (Stl).

Cell 8B. a 63', w E 28', f 124' 549t. FPT 44t, APT 42t.

FK, 43H, Cem, Lloyd's A+C.P., P 21', B 68', F 29'.

A.W.J.

3/5/23.



© 2021

Lloyd's Register
Foundation

012460-012472-0009