

LLOYD'S REGISTER OF SHIPPING

No. 32

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name M.S. " NORWID " Official No. _____

Port of Registry Gdynia

This ship has been under survey at Gdynia

on 4th & 8th March 196⁶ and the following alterations to the conditions of

assignment of loadlines have now been effected/found:—

- a) O.S.D. freeboard marks painted and verified and C.S.D. marks obliterated.
- b) Tonnage hatch on shelter deck closed with efficient temporary wood covers secured by hemp lashings.
- c) Freeboard deck hatches, beams, covers, tarpaulins and wedges examined and found in good condition.
- d) Scuppers from tonnage well overboard and tween decks to hold bilges controlled from above shelter deck with indicators all found in good condition.
- e) Tonnage openings in tween deck ~~bhds~~ steel plates secured by hook bolts spaced more than 12" apart (packing removed).

Handwritten signature and date: 1/11/66

Handwritten signature
.....
E. T e e
Surveyor to Lloyd's Register
of Shipping

A copy of this Report has been placed on board.

012616 - 012619 - 0055

