

2.0.

NAME OF VESSEL ..... NELLY .....

Extract from freeboard verification of marking form received from the Maples Surveyors dated ..... 14.12.49

Moulded depth	<u>42</u> ft.	<u>6</u> ins.
Corresponding draught	<u>22</u> ft.	<u>3</u> ins.
Moulded depth as shewn on draught sheet	<u>42</u> ft.	<u>6</u> ins.
Tropical freeboard	<u>20</u> ft.	<u>4<sup>3</sup>/<sub>4</sub></u> ins.
Summer "	<u>20</u> ft.	<u>4<sup>3</sup>/<sub>4</sub></u> ins.
Winter "	<u>20</u> ft.	<u>4<sup>3</sup>/<sub>4</sub></u> ins.
W.N.A. "	<u>—</u> ft.	<u>—</u> ins.
Fresh Water allowance	<u>5<sup>1</sup>/<sub>2</sub></u> ins.	

Marked from ~~wood~~ / steel upper deck

Checked by J.S.  
Dated ..... 18/1/50 .....