

NAME OF VESSEL ..... *Panay* .....

Extract from freeboard verification of marking form received  
from the ..... *Vancouver* ..... Surveyors dated the *22. 3. 46* .....

Moulded depth	<i>14</i> ft.	<i>1</i> ins.
Corresponding draught	<i>14</i> ft.	<i>0<math>\frac{1}{4}</math></i> ins.
Moulded depth as shown on draught sheet	<i>14</i> ft.	<i>1</i> ins.
Tropical freeboard	<i>0</i> ft.	<i>5</i> ins.
Summer "	<i>0</i> ft.	<i>5</i> ins.
Winter "	<i>0</i> ft.	<i>8<math>\frac{1}{2}</math></i> ins.
W. H. A. "	<i>0</i> ft.	<i>10<math>\frac{1}{2}</math></i> ins.
Fresh water allowance	<i>3<math>\frac{1}{2}</math></i>	ins.

*3' cant up of*  
Marked from ~~wood~~/steel upper deck.

*[Signature]*

Checked by *JM* .....

Dated ..... *11. 7. 46* .....



© 2021

Lloyd's Register  
Foundation

012966-012982-0103