

See paid

F.E.
(FBD.)

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel Sc. S.S. "BRASTED"

Rpt. _____ Lth. No. 19487
Nwc. 95876.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No.	3164	Depth "d"	10.85 to Upper dk. 14.35 to R.Q.Dk.
2nd Long. No.	10674	Proportions = $\frac{L}{D}$	-
Framing Bulb angle frames as approved	Sheerstrake		As approved

The Newcastle Surveyors report the Special Survey completed.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~100A1~~ "With Freeboard"

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

1 Dk.
 Cell.DB 172' 368t, FPT 91t, APT 28t.
 FK, 4BH., cem., Lloyd's A & CP.
 Q 156', F 25'
 Machy. aft
 O.L. 229'-7".

The Certificate of Classification to be endorsed "*Cargo battens not fitted*" and the same notation to be printed in the Register Book.



Jan
4.2018

© 2021
Lloyd's Register
Foundation
013260-013267-0127