

-40

as fitted..... as per Rule..... as fitted.....
Is the } tube } shaft fitted with a com

Engine No. 2934 Made by North Eastern Mar. Eng Co.
Boiler

For Hong Kong & Whampoa S.S. Co. Ltd. No. 819

Survey Report No. 97653

It is submitted that a copy of this Report be
forwarded to the ~~returned~~ to the *St. Reg.* Surveyors for their
guidance and for completion.

Date

24/2/39

1m,11,38.

10 AUG 1939

© 2021
Lloyd's Register
Foundation
013390-013396-0250

What Pipes pass through the owners

What pipes pass through the deep tanks

Have they been tested as per Rule