

CONDITION OF CLASS. TONNAGE OPENING FITTED.

NAME OF VESSEL... "HERMISTON".....

Extract from freeboard verification of marking form received

from the ..... SUNDERLAND ..... Surveyors dated the 10.10.39 -

Moulded depth 26 ft. 7 ins. ✓

Corresponding draught 24 ft.  $2\frac{1}{4}$  ins. ✓

Moulded depth as shewn  
on draught sheet 26 ft. 7 ins. ✓

Tropical Freeboard 2 ft.  $1\frac{3}{4}$  ins. ✓

Summer " 2 ft.  $7\frac{3}{4}$  ins. ✓

Winter " 3 ft.  $1\frac{3}{4}$  ins. ✓

W.N.A. " - ft. - ins. ✓

Fresh Water allowance  $6\frac{3}{4}$  ins. ✓

Marked from ~~xxxxx~~/steel upper deck.

Checked by..... *pm*.....

Date... 31.10.39.....



© 2021

Lloyd's Register  
Foundation

013545-013552-0009