

~~copy~~

Ship's name

"JOSINA"

Port

Val.

No 2049

Last survey date 7.11.65.

Class is subject to a bower anchors being verified with test certificates at the earliest opportunity.

S.R.L. Appendix (as before ~~xxxxxxxxxx~~)

Nature of present survey (afloat ~~xxxxxxxxxxxxxxxxxx~~)

Temporary repairs to damage on account of explosion in O.F. deep tank.

Recommendation

SUBJECT as above, and to damaged O.F deep tank (p.s) and structure in way being permanently repaired on arrival at Sevilla. *Just*

As Now. Subject

IN S.R.L. APPENDIX  
Shell plates B, A, C.4 & 5,  
D.2,3,4 & 5 (s.s.a) indented.

TO NOTE		TRO
S. PLANS	S. RESEARCH	S. DEVELOP.
E. REPORTS		PUBS.

NOTE:- The Cadiz Surveyors report ship now under survey.