

NAME

Josina

REPORT

Barcelona No. 5501

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in hundredths of an inch mm.

	AMIDSHIP.					FORWARD.					AFT.					REMARKS.
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
L	15.7	15.2	15	.5	.7	9.5	9	9	.5	.5	9.5	11	11.5	-	-	Bdgy. 62 36 38
K	14.3	10	7	4.3	7.3	9.5	9	9	.5	.5	9.5	7	10	2.5	3	86 36 38
J	15.7	12	11.5	3.7	4.2	14.3	13	13.5	1.3	.8	14.3	15	15	-	-	80-46 (42 plks)
H	15.7	12	12.5	3.7	3.2	11.7	12	12	-	-	11.7	12.2	10	-	1.7	60-42
G	15.2	13	11	2.2	4	12.7	12	11	.7	1.7	12	11.7	12.5	.3	-	60-46 (42 plks)
F	15.2	8	12	7.2	3.2	12.7	10.5	10.5	2.2	2.2	12	10.5	11.5	1.5	.5	
E	14.7	12	11.5	2.7	3.2	12.7	11	13	1.7	-	13	11	10.5	2	2.5	70-3 plate
D	cemented					14.7	12	11.5	2.7	3.2	12	12	11.5	-	.5	70-3 plate 88-44
C						12.7	8	0	4.7	-	11	10	10.5	1	.5	86-44
B																
A	Remarks.- Drillings have been taken 2 frame spaces fore and															
94	aft of collision and after peak bulkheads respectively.															
Original thicknesses have been taken from shell																
expansion plan.																
Signature																

Drillings at ends to be made in the vicinity of the peak bulkheads.

013950-013960-0162