

10. MAY 1965

Ship's Name SS/MS "EMPIRE GANNET". LR 510367. Gross tons 4260.
 Date of Build: 3-1945. Port of Registry: London.
 Is there a rpt. 9? Yes. Port HONG KONG. Rpt. No. 19352.

No. of visits Three. First date 17-4-65. Last date 26-4-65.
 Interim Cert. issued & copy herewith? Yes. Damage rpt. issued & copy herewith? No. Last rpt. (H.Q. only) S-15 17888
 Date of completing rpt. 29-4-65. Surveyed at, if different from Port above --
 Surveyed afloat and/or in D.D. Both. Last date of examination in D.D. 21-4-65.
 Has a Load Line Survey been held? No. Summer Freeboard ^{as} ~~Mark~~ verified No.

State which additional Rpt. 8 is attached: ~~(Cont)~~; (PS); ~~(DP)~~; ~~(EQ)~~; ~~(Rig)~~

Survey fees Damage fee -- Expenses \$30.00
 D.S. \$250.00

S.A. fee --

I have surveyed the above ship in accordance with the Rules for DOCKING SURVEY.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Docking Survey :-

Shell plating, sternframe & rudder cleaned, examined and recoated.

Shell and weather decks specially examined.

Wear & Tear repairs :-

Starboard side aft abreast after hatch: stringer, 1st inboard and 2nd inboard strakes of weather deck plating renewed.

S.R.L. :- None.

S.R.L. Appendix :- Nothing done.

I recommend that this ship remain as classed with/without fresh record of dry docking 4,65, subject to any outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

TUESDAY 1 JUN 1965

DS 4.65
 MBS 4.65

write H/KG (m)

E.L. Green. E.L. Green.
 Surveyor to Lloyd's Register of Shipping

FOR CHAIRMAN
 CLASSN. CITE

ALSO FOR

SPL FOR

C.S.S.

RECORDS

TBC

SRL

POSTING

HEADER

CERT

Lloyd's Register
 Foundation

014091-04048-0243 1/2

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

Ship's Name SS/MS "EMPIRE GANNET". LR 510367. S.S. () Due

Port HONG KONG. Rpt. No. 19352.

<u>Examined & condition</u>		<u>Examined & condition</u>	
In dry dock from	16-4-65.	* Air & sounding pipes	(above deck) - Good.
" " " to	21-4-65.	Doublers under " "	Not Examined.
Shell plating	Good.	Steering arrangements (main)	Good.
Sternframe	Good.	" " (aux)	Good.
Rudder	Good.	Windlass	Good.
Was rudder lifted?	No.	Standing	
Plating, etc. in way		Masts & rigging	Not Examined.
of shell openings	Good.	Hand pumps & suction	Not Examined.
Side scuttles		W.T. doors	Not Examined.
& deadlights	Not Examined.	Bulwarks, freeing ports, etc.	Not Examined.
Overbd. scuppers			
& discharges	Not Examined.		
F.P. spaces	Not Examined.		
Chain locker	Not Examined.	Summer freeboard	as verified
A.P. spaces	Not Examined.		
Engine space	Not Examined.		
Boiler space	Not Examined.		
Under E. & B.	Not Examined.	<u>EQUIPMENT:</u>	
Coal bunker	Not Examined.	Equipment letter	1½" ptWI ptSQ.
Tunnel & well	Not Examined.	Fee ltr., if diff. from eqpt. ltr.	(v).
Cement, asphalt,		Anchors: No. on board	3 B.
etc., on btm. shell	Not Examined.		
Weather decks	Not Examined.	State if ranged	No.
* Casings	Not Examined.	Length on board	
* Deckhouses	Not Examined.	Mean dias. range from	to
* Superstructures	Not Examined.	Rule length	Dia.
* Skylights	Not Examined.	Mooring ropes	
* Companionways	Not Examined.		
* Hatchways	Not Examined.		
* Ventilators	Not Examined.		
Other items:	--		

* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"