

COPY

Ship's name

Ilyaskaksh.

Port

Krk

No.

653

Class is subject to

*Nil
Repairs*

Last survey date

5.12.64

Ballast pump water end of 01 corroded at cylinder bottom & in way of valve seats, now temporarily repaired. It is recommended ballast pump water end be renewed by end of 5 65. Considered efficient seaworthy.

ham circulating pump discharge pipe bend fractured in way of 3 brazing now repaired & reinforced. It is recommended main circulating pump discharge pipe being renewed by 5 65.

It is submitted that this vessel is eligible to remain as CLASSED.



© 2021

8/65
Lloyd's Register
Foundation