

REPORT of SURVEY for REPAIRS, &c.

4233

No. 4233 Date of Writing Report June 5 1891 Port of Munden
 No. in Survey held at Munden Date, First Survey June 2 Last Survey June 4 1891
 Reg. Book 369 on the Steam Trawler, North-East (No. of Visits 2) Master A Mackenzie

MON. 8 JUN 1891

TONNAGE:—
 NET 25 Built at Munden By whom Hall Russell & Co When 1890 8
 GROSS 123 Owners H. Piper Port belonging to Munden
 UNDER DK. /// Owners Address _____
 (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Slipway Name of Dock Small Slip Destined Voyage Fishing
 Length of Poop _____ ft.: of Forecastle _____ ft.: of Raised Qr. Deck _____ ft.: Moulded Depth _____ ft. _____ ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 4111 Port Abn Classed L. No. 68.90 / 100 A. 1. 8.90
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) in Summer _____ ft. _____ ins.
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) as painted on Ship in Winter _____ ft. _____ ins.
 of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Lighting bottom

The vessel placed on the above slipway and the bottom examined and found in good condition and afterwards repainted

PRESENT CONDITION OF THE		Blank (Bottom) & Counter		Ceiling		Boats	
Decks	<u>Good</u>		<u>Good</u>		<u>Good</u>		<u>Good</u>
Waterways	"	Treenails or Rivets	"	Rudder	"	Masts, Yards, &c.	"
Comings	"	Breasthooks & Stems	"	Windlass & Capstan	"	Condition, how ascertained	<u>found</u>
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	"
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"	Anchors No. of	<u>3</u>
Planksheers	"	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Wat'rways	"	Cables	"
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	"	Hawsers & Warps	"
Topsides	"	Clamps & Shelves	"	When put on	"	Standing & Running Rigging	"
Wales	"					Hatches	"
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c.	"	Scuppers	"	Cargo & Main Hatchways	"

General Observations, Opinion as to Class, Recommendation, &c. :
This vessel so far as seen is in good and efficient condition and eligible in my opinion to remain as classed and to be noted. 6-91 in the Register Book

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	18
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	Received by me,
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	18
Second Surveyor's Fee (if any)	£	:	:	

G. S. Hindmarsh
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute TUES. 9 JUN 1891
 Character assigned 100 A 1 Trawler

State if a Report is also sent on the Machinery of the Ship - or if not, whether, and when, one will be sent.

Form No. 2 for Repairs - 10000 - 5/7/91. - Transfer in T. & S. - Certificate to be sent to Committee's Minute. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

