

# REPORT of SURVEY for REPAIRS, &c.

Received in London Office.

No. 3675

No. in Reg. Book.

Survey held at

Aberdeen

Date, First Survey

Last Survey

11 May 1886

(No. of Visits)

Master

James Scott

YEAR

MONTH

TONNAGE:—

NET

106

GROSS

169

UNDER DK. 138

Built at

N Shields

By whom

T. W. Smith

When

1884-11

Owners

Crawford & Co

Port belonging to

Grangemouth

Owners' Address

Grangemouth

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Afloat

Name of Dock

Aberdeen

Destined Voyage

Length of Poop

ft. of Forecastle

ft. of Raised Or. Deck

ft. of Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Classed

100 A1  
2-86

Last Survey, No.

Port

Gmk

State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.

Society's Freeboard (if assigned)

in salt water

ft.

ins.

as painted on Ship

in fresh water

ft.

ins.

REPAIRS, OR EXAMINATION AS PER RULE

Damage through Collision

On the Star Side

for about 10

The bow plate in way of fore peak cracked

The Captain states that the plate will be

renewed at Grangemouth.

## PRESENT CONDITION OF THE

Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (If Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, &c.:

The Surveyors at Leith have been advised that the damage will be made good at Grangemouth.

Entry Fee (if chargeable) per Scale I., Sec. 27.

£

Office Fee (if chargeable) per Scale II., Sec. 27.

£

Survey Fee (per Section 28)

£

Special Damage Fee (if any) (per Sec. 28)

£

\*Certificate (if required) to be sent to per margin

£

Travelling Expenses (if chargeable)

£

Second Surveyor's Fee (if any)

£

received by me,

188

John H Heck

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

Not case

TUESDAY 19 MAY 1886

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.

Lloyd's Register Foundation

ABN8-0255