

REPORT of SURVEY for REPAIRS.

No. 64 Survey held at Glasgow Date 5th March 1848
 on the Ship "Caledonia" Master Alexander Greenhorn
 Tonnage 383 Built at Glasgow When built 1841
 By whom built 438 Owners Alban & Co.
 Port belonging to Glasgow Destined Voyage Montreal
 If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 1925 Classed 10.A.1.

Port Ch. de

REPAIRS At Present. Shipped the Copper and Wood Sheathing below the Wale and cleared the Bottom.
Renewed Vane sheet after having on the Starboard Buttock and on the Starboard Buttock with English Oaks. Caulked the Bottom from Keel to Wale. Replaced the Wood sheathing (Six Strakes) port below the Wale and Caulked it.
Resheathed the Bottom with Yellow Metal over Paper below, and upper Course over felt.

Present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound and</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>In Good Condition</u>
Lower Deck Beams & Fastenings <u>Sound</u>	Keelsons <u>do</u>	Sails <u>Complete and Good</u>
Planksheers <u>good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 1/2" 1 1/2" 1 1/2"</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete and Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Yellow Metal Slip</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, This Ship is in very good condition throughout and is suitable for the safe conveyance of Dry and Perishable Cargo to and from all parts of the World and can be continued as before.

Wm. Robertson

Amount of Fee, £ 3 : 0 : 0 is received by me,

Certificate (if required) - : - : -

Minute 14th March 1848

assigned 10

Wm. Robertson



© 2019

Lloyd's Register Foundation

1900-041576