

# ANNUAL SURVEYS.

443

No. 443 Survey held at Glasgow Date 18<sup>th</sup> February 1851  
 on the Barge "Ann Harley" Master Robert Craig  
 Tonnage 455 Built at Mirimachi When built 1844  
 By whom built \_\_\_\_\_ Owners Reid & Murray  
 Port belonging to Glasgow Destined Voyage New York  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 148 Port of Glasgow Classed F. 1  
S. S. = 49 = 4

The present Condition of the

Decks <u>In Good Condition</u>	Treenails <u>Where Seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>2</u> <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>3</u> <u>do</u>
Upper Deck Beams & Fastenings <u>Sound &amp; Firm</u>	Timbers of the Frame <u>Where Seen do</u>	Masts, Yards, &c. <u>Complete and Good</u>
Lower Deck Beams & Fastenings <u>Firm</u>	Keelsons <u>do</u>	Sails <u>do</u> <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B. 1 Stm. 1 Hedge</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete and Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u> <u>do</u>
Wales <u>do</u>	Copper <u>1 Metal</u> When put on <u>1848</u> <u>do</u>	Standing & Running Rigging <u>do</u> <u>do</u>
Plank (Bottom) and Counter <u>Where Seen do</u>		

General Observations and Opinion, At Present Caulked from the Sheathing to the Gunwale  
Is in good Condition and may continue as Classed

*Richd Robertson*

Committee Minute 4<sup>th</sup> March 1851  
 Character assigned F. 1

Certificate (if required)

No. 443 Survey held at Glasgow Date 21<sup>st</sup> February 1851  
 on the Ship "Caledonia" Master William Allan  
 Tonnage 383 Built at Greenock When built 1841  
 By whom built 438 Owners Allan & Co.  
 Port belonging to Greenock Destined Voyage Montreal  
 If Surveyed Afloat or in Dry Dock Patent Ship

Last Survey, No. 185 Port of Glasgow Classed 10.A.1

The present Condition of the

Decks <u>In Good Condition</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>4</u> <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>3</u> <u>do</u>
Upper Deck Beams & Fastenings <u>Sound &amp; Firm</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>Complete and Good</u>
Lower Deck Beams & Fastenings <u>Firm</u>	Keelsons <u>do</u>	Sails <u>do</u> <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B. 1 Stm. 1 Hedge</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete and Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u> <u>do</u>
Wales <u>do</u>	Copper <u>1 Metal</u> When put on <u>1848</u> <u>do</u>	Standing & Running Rigging <u>do</u> <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, Patched the Yellow Metal Sheathing where necessary  
Is in good Condition and may continue as Classed

Committee Minute 4<sup>th</sup> March 1851  
 Character assigned 10 A. 1

*Richd Robertson*  
 © 2019  
 Lloyd's Register  
 Foundation  
 Certificate (if required)

GLS140-0414