

REPORT of SURVEY for REPAIRS.

No. 498 Survey held at Glasgow Date 23rd July 1857
 on the Ship "Albion" Master John Barclay
 Tonnage 414 Built at Greenock When built 1845
 By whom built 471 Owners Allan & Co.
 Port belonging to Greenock Destined Voyage Montreal
 If Surveyed Afloat or in Dry Dock Patent Ship

Last Survey, No. 444 Port Glasgow Classed 10 A, 1
2, 57

REPAIRS Of damage

At Present stripped the Copper Sheathing and Cleaned
the Bottom, repaired the Knee of the Head, put in a short piece of Bilge
Plank on the Starboard Side
Caulked from the keel to the Wales and Resheathed the Bottom with Copper over
Paper

Present Condition of the

Decks <u>in Good Condition</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound & Firm</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>Complete & Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 Br 1 Star 1 Kedge</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete & Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do do</u>
Wales <u>do</u>	Copper <u>New</u> When put on <u>July 1857</u>	Standing & Running Rigging <u>do do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, No in good & efficient Condition and fit for the safe Conveyance
of dry and Perishable Cargoes to and from all parts of the World and may
Continue as Classed

Wm B. Rutton

The Amount of Fee.....£ 2 : : : is received by me,

Special Damage 2 : 2 : "

Certificate (if required) " : : : "

Committee's Minute 5th Aug 1857

Character assigned 10 A, 1 Good



© 2019

Lloyd's Register
 Foundation

GLS/40-0462