

892

Last Survey, No. *771* Port *Glasgow* Classed *W. F. 1.*
Port 50 3 8

Present Condition of the		When put on	
Decks	Good	Treenails	Good
Waterways	do	Breasthooks and Stemson	do
Comings	do	Transoms, Pointers, and Crutches	do
Upper Deck Beams & Fastenings	do	Timbers of the Frame	do
Lower Deck Beams & Fastenings	do	Keelsons	do
Planksheers	do	Clamps and Shelves	do
Sheerstrakes	do	Ceiling	do
Topsides	do	Rudder	do
Wales	do	Copper	Good
Plank (Bottom) and Counter	When put on	When put on	1853
Windlass and Capstan	Good	Pumps	2 Bellair & 2 Bilge do
Boats	2 do	Masts, Yards, &c.	do
Sails	do	Anchors	No. of 3 1/2 1 Star & 1 Hedge
Cables	Complete & Good	Hawsers and Warps	do do
Standing & Running Rigging	do do		

Plank (Bottom) and Counter ~~When put on~~
General Observations and Opinion, We have Specially Survejed this Vessel in Accordance
with the Rules Sections 57 & 60 and are mutually of opinion that she is
in good Condition and fit for the safe Conveyance of Dry and Perishable
Cargoes to and from all parts of the World and that she may be Classed

Wm. D. Burton
John R. Curran

John R. Curran

4th April 1852

4th Apr 1834
 1st ~~AL~~ 1st Month 35 18th 1834