

ANNUAL SURVEYS.

1392

No. 1392 Survey held at Glasgow Date 9th October 1857
on the Schooner Archibald Master Robert Walker
Tonnage 11 Built at Bowling Bay When built 1839
By whom built McLean & Lament Owners McLean & Lament
Port belonging to Glasgow Destined Voyage Spain
If Surveyed Afloat or in Dry Dock Patent Ship

Last Survey, No. 1216 Port of Glasgow Classed 8 *F. 1 S.S. 53
Rest 47-5 Yrs 56

The present Condition of the			
Decks	<u>Good</u>	Treenails	<u>When Seen, Fair & Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>Not Seen</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame	<u>When Seen Good</u>
Lower Deck Beams & Fastenings	<u>do</u>	Keelsons	<u>do</u>
Planksheers	<u>Good</u>	Clamps and Shelves	<u>do</u>
Sheerstrakes	<u>do</u>	Ceiling	<u>do</u>
Topsides	<u>do</u>	Rudder	<u>do</u>
Wales	<u>do</u>	Copper	<u>zinc</u> When put on <u>1855</u>
Plank (Bottom) and Counter	<u>When Seen do</u>		
		Windlass and Capstan	<u>Good</u>
		Pumps	<u>do</u>
		Boats	<u>do</u>
		Masts, Yards, &c.	<u>do</u>
		Sails	<u>Part New & Good</u>
		Anchors	No. of <u>2 Br 1 Iron Wedge</u>
		Cables	<u>Good</u>
		Hawsers and Warps	<u>do</u>
		Standing & Running Rigging	<u>do</u>

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Some New & Good
Caulked from zinc sheathing to Manchester, Waterway, Seams and
Round Heads of Stanchions, Ceiling Patched; Some new Treenails in both
Sides; As now in good Condition fit for the safe Conveyance of Dry and
Perishable Cargoes to and from all parts of the World and may

Committee's Minute 20th October 1857 Continue as before
Character assigned B. 1 asterisk

Wm. D. Lister

Certificate (if required)
GLS 142-0164

Lloyd's Register
Foundation