

ANNUAL SURVEYS.

1599

Recd 29/9/59

No. 1599 Survey held at Glasgow Date 19th September 1859
 on the Ship "City of Edinburgh" Master Richard Roden
 Tonnage 549 Built at Glasgow When built 1852
 By whom built Barclay & Crole Owners George Smith & Sons
 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Patent Ship

Last Survey, No. 1499 Port of Glasgow Classed 13A.1

The present Condition of the

Decks Good Where Seen
 Waterways do
 Comings do
 Upper Deck Beams & Fastenings do
 Lower Deck Beams & Fastenings do
 Planksheers do
 Sheerstrakes do
 Topsides do
 Wales do
 Plank (Bottom) and Counter do

Treenails Good Where Seen
 Breasthooks and Stemson do
 Transoms, Pointers, and Crutches do
 Timbers of the Frame do
 Keelsons do
 Clamps and Shelves do
 Ceiling do
 Rudder do
 Copper Painted When put on Sept 1859

Windlass and Capstan Good
 Pumps 4 in dia do
 Boats 3 do do
 Masts, Yards, &c. Complete & Good
 Sails do do
 Anchors No. of 3 1/2 1 1/2 1 1/2 1 1/2
 Cables Complete & Good
 Hawser and Warps do do
 Standing & Running Rigging do do

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Shipped the Yellow Metal Sheathing, Cleaned the Bottom and Caulked from Keel to Upper part of Wales and Sheathed with Yellow Metal over Paper; is now in good & efficient condition and may continue as Chased

Committee's Minute 30th September 1859

Character assigned 13A.1

recd W. M. L. P.

Certificate (if required)

No. 1599 Survey held at Glasgow Date 21st Sept. 1859
 on the Ship "Mary Allan" Master William Cunningham
 Tonnage 241 Built at Perth When built 1842
 By whom built 257 Owners William Milne
 Port belonging to Glasgow Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Patent Ship & Afloat

Last Survey, No. 3890 Port of Clyde Classed 9A.1.58

The present Condition of the

Decks Good Where Seen
 Waterways do
 Comings do
 Upper Deck Beams & Fastenings do
 Lower Deck Beams & Fastenings do
 Planksheers do
 Sheerstrakes do
 Topsides do
 Wales do
 Plank (Bottom) and Counter do

Treenails Good Where Seen
 Breasthooks and Stemson do
 Transoms, Pointers, and Crutches do
 Timbers of the Frame do
 Keelsons do
 Clamps and Shelves do
 Ceiling do
 Rudder do
 Copper Painted When put on 1858

Windlass and Capstan Good
 Pumps 4 in dia do
 Boats 2 do do
 Masts, Yards, &c. Complete & Good
 Sails do do
 Anchors No. of 3 1/2 1 1/2 1 1/2 1 1/2
 Cables Complete & Good
 Hawser and Warps do do
 Standing & Running Rigging do do

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Bottom Examined. A few Sheets of Yellow Metal off and renewed. Appears to be in good condition and fit for the safe conveyance of Dry and Perishable Cargo to and from all parts and may

Committee's Minute 30th September 1859

Character assigned Rest 13A.1

L. P.

Certificate (if required)

See for Charge of Owners