

REPORT of SURVEY for REPAIRS.

1740

Rev 1/10/60

No. 1716 Survey held at Glasgow Date 24th & 26th Sept 1850
 on the Ship "Hallyards" Master John Wright
 Tonnage 299 Built at Port Glasgow When built 1818
 By whom built Owners Campbell
 Port belonging to Glasgow Destined Voyage Vinidad
 If Surveyed Afloat or in Dry Dock Patent Slip

Survey, No. 22213 Port London Classed — A — SS 63-6 yrs
 Rest 38-6 yrs C 2 58

At present shipped three Upper Courses of Yellow Metal

renewed, the fore Length of Wale Plank on Starboard Bow
 One on Starboard Quarter with Quebec Oak, drove out all the
 at Bolt to hold beam hanging knees and renewed them
 a number of Stinger Bolt
 the Wale and Upper Courses of Bottom were shipped
 and Resheathed with Yellow Metal over Iron

at Condition of the

Good	Treenails	Good	Windlass and Capstan	Good
do	Breasthooks and Stemson	When seen do	Pumps 4 in str	do
do	Transoms, Pointers, and Crutches	do do	Boats 3	do
do	Timbers of the Frame	do do	Masts, Yards, &c.	Complete & Good
do	Keelsons	do do	Sails	do do
do	Clamps and Shelves	do do	Anchors No. of 3 1/2 in 1 stem 1 Wedge	
do	Ceiling	do do	Cables	Complete & Good
do	Rudder	do	Hawsers and Warps	do do
do	Copper	When put on 1837/8 Port 1860	Standing & Running Rigging	do do
do	Caulking of Bottom, Deck, & Waterways.	Good		

Observations and Opinion,

in good Condition fit for the safe Conveyance of dry and
 perishable Cargoes and may be Classed A. 1.

The Amount of Fee.....£ / : : is received by me,

Special..... / : : :

Certificate (if required) : : 5 : :

Committee's Minute 2nd October 1850

Character assigned A. 1

Record Officer



Deferred
 © 2019 Surveyor
 Lloyds Register
 Foundation
 GLS 142 - 0401