

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 2329** Survey held at Glasgow Date 22<sup>nd</sup> April 1865  
on the Ship "Albion" Master J. Shaw  
Tonnage 414 Built at Greenock When built 1845  
By whom built 471 Owners William & Co  
Port belonging to Glasgow Destined Voyage Buenos Ayres  
If Surveyed Afloat or in Dry Dock Patent Slip Stephen & Son

Last Survey, No. 1881 Port Glasgow Classed W.A. 1. 62.

REPAIRS Stripped the Yellow Metal Sheathing, Brightened the Bottom, Recaulked from Keel to Metal Line and Bottom Re-sheathed with Yellow Metal on Sill to 16 feet, Main Deck Scupper all renewed with Lead

Present Condition of the

Decks <u>Where Seen Good</u>	Treenails <u>Where Seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto Ditto at other places <u>do</u>	Sails <u>do</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Anchors No. of <u>3134 1st 2nd Wedge</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Cables <u>Complete</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>	Copper <u>When put on 1865</u>	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Now & Good Where Tested  
As in good Condition Eligible to remain as Classed

The Amount of Fee.....£ " : " : " is received by me,  
Special..... / : / : "  
Certificate (if required) " : " : "

Committee's Minute 28<sup>th</sup> April 1865  
Character assigned Rest 7 A 1

Robt. Maclean