

REPORT of SURVEY for REPAIRS, &c.

No. 8489 Date of Writing Report 188 Port of Glasgow
 No. in Reg. Book. Survey held at Glasgow Date, First Survey 4th April Last Survey 21 April 1888
 852 on the Iron S.S. Clan Stuart Master Whyte

TONNAGE:—
 NET 1355 Built at Dumbarton By whom A. McMillan & Son When 1879-2
 GROSS 2094 Owners Cargill, Irvine & Co Port belonging to Glasgow
 UNDER DECK 1911 Owner's Address Glasgow
 If Surveyed Afloat or in Dry Dock Dry Name of Dock Govan Destined Voyage S. of America
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth 25 ft. 6 ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 100A1 Port S. of America 1887
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) as painted on Ship)
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.
 in Summer 4 ft. 11 ins.
 in Winter 5 ft. 2 1/2 ins.
 Fresh water less 5 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Repainting &c.
 This vessel placed in dry dock. bottom sighted. scraped and repainted. and Green D^{rs} from E. B. & aft also cleaned & repainted. The Chain cables ranged.
 The Freeboard intimated in Secy's letter 19/4/88 has now been marked on the vessel's sides in accordance with Circular No. 574.

CONDITION OF THE	Plating	Food	Ceiling	Food	Boats	Food
Planks	Plank (Bottom) & Counter	✓	Rudder	✓	Masts, Yards, &c.	✓
Waterways	Trunnions or Rivets	✓	Windlass & Capstan	✓	Condition, how ascertained	From D ^{rs}
Stairways	Breasthooks and Stemson	✓	Pumps	✓	Sails	Food
Beams & Fastenings	Transoms, Pointers, & Crutches	✓	Cement (if Iron Ship)	✓	Anchors No. of	3 B. 15.2 K.
Ke. Beams & Fastenings	Timbers of Frame at the opening	✓	Caulking of Bot'm, D'k, & Watrways	✓	Cables	270 fathoms
Sheers	ditto ditto at other places	✓	Copper, or Y.M. (State if on Felt.)	✓	Hawsers & Warps	✓
Strakes	Keelsons	✓	When put on	✓	Standing & Running Rigging	✓
Sides	Clamps & Shelves	✓	Scuppers	Food	Hatches	✓
Engine room Skylights	Coal Bunker, Openings, Lids, &c.	Food	Cargo & Main Hatchways	Food		

General Observations, Opinion as to Class, Recommendation, &c.:
 This vessel appears to be in good Condition and is in my opinion eligible to remain as classed.
 I have also to recommend that the Freeboard be now recorded in the Register Book.

Entry Fee (if chargeable) per Scale I., Sec. 27... £ :
 Office Fee (if chargeable) per Scale II., Sec. 27... £ :
 Survey Fee (per Section 28) £ :
 Special on Damage, Fee (if any) per Sec. 28... £ :
 Certificate (if required) to be sent as per margin £ :
 Travelling Expenses (if chargeable) £ :
 Second Surveyor's Fee (if any) £ :
 Fees applied for, 188
 Received by me, 188
 Surveyor to Lloyd's Register of British & Foreign Shipping.
 Committee's Minute
 Character assigned 100A1
 L M C 4/88
 FRIDAY 27 APRIL 1888
 Record Freeboard