

REPORT of SURVEY for REPAIRS, &c.

No. 9841

Date of Writing Report

18

Port of Glasgow

Received in London Office,

WED 4 JUNE 1890

No. in Reg. Book.

Survey held at Glasgow

Date, First Survey 26th May

(No. of Visits)

Last Survey 30th May 1890

497 on the Iron Steamer "Portland"

Master J. Crawford

TONNAGE:—

NET 531

GROSS 1103

UNDER DK. 949

Built at Dundee

By whom W. B. Thompson

When 1887

Owners Clyde Shipping Co.

Port belonging to Glasgow

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Slipway Name of Dock Inglis

Destined Voyage coasting

Length of Poop

ft. of Forecastle

ft. of Raised Or. Deck

ft. of Moulded Depth

ft. ins.

(if these particulars are not yet recorded in the Register Book.)

Classed

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No. 9209 Port Gls.

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

in Summer ft. ins. in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Painting bottom

This vessel has been placed on slipway the bottom cleaned and coated, about 90 ft of iron rubbing plate 6" x 1 1/2" fitted at upper turn of bilge on port side.

PRESENT CONDITION OF THE

| | | | | | | | |
|------------------------------|------|----------------------------------|------|-------------------------------------|------|----------------------------|--------------|
| Decks | good | Plank (Bottom) & Counter | good | Ceiling | good | Boats | good |
| Waterways | " | Transverse Rivets | " | Rudder | " | Masts, Yards, &c. | " |
| Comings | " | Breasthooks and Stemson | " | Windlass & Capstan | " | Condition, how ascertained | from deck |
| Up'r Dk. Beams & Fastenings | " | Transoms, Pointers, & Crutches | " | Pumps | " | Sails | good |
| Low'r Dk. Beams & Fastenings | " | Timber of Frame at the opening | " | Cement (if Iron Ship) | " | Anchors No. of | SB-15-25 |
| Planksheers | " | Ditto ditto at other places | " | Caulking of Bot'm, D'k, & Watrways | " | Cables | put new good |
| Sheerstrakes | " | Keelsons | " | Copper, or Y.M. (State if on Felt.) | ✓ | Hawsers & Warps | good |
| Topsides | " | Clamps & Shelves | ✓ | When put on | ✓ | Standing & Running Rigging | " |
| Wales | " | | | | | Hatches | " |
| Engine Room Skylights | " | Coal Bunker, Openings, Lids, &c. | good | Scuppers | good | Cargo & Main Hatchways | good |

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel is in a good and efficient condition and in my opinion eligible to remain as classed and have record of survey Gls 5.90

| | | | | |
|--|---|---|---|----------------------|
| Entry Fee (if chargeable) per Scale I., Sec. 27... | £ | : | : | Fees applied for, 18 |
| Office Fee (if chargeable) per Scale II., Sec. 27... | £ | : | : | |
| Survey Fee (per Section 28) | £ | : | : | |
| Special on Damage, Fee (if any) (per Sec. 28) | £ | : | : | |
| *Certificate (if required) to be sent as per margin | £ | : | : | |
| Travelling Expenses (if chargeable) | £ | : | : | |
| Second Surveyor's Fee (if any) | £ | : | : | Received by me, 18 |

Committee's Minute FRI 6 JUNE 1890
Character assigned 100 A.1

Surveyor to Lloyd's Register of British & Foreign Shipping.