

# REPORT of SURVEY for REPAIRS, &c.

No. 9939

Date of Writing Report

18

Port of

Glasgow

Received in London Office, THURSDAY 3 JULY 1890

No. in Reg. Book.

Survey held at

Glasgow

Date, First Survey

26<sup>th</sup> June

Last Survey

30<sup>th</sup> June 1890

556

on the

S.S. Bonnington

(No. of Visits)

Master

McIlne

YEAR. MONTH.

TONNAGE:—

NET 1332

GROSS 2059

UNDER DECK 1999

Built at Glasgow

By whom

R. Duncan & Co

When 1883

Owners

S.S. Bonnington Co (Lim)

Port belonging to

Glasgow

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock

Afloat

Name of Dock

Queens

Destined Voyage

Cape Route

Length of Poop

ft. of Forecastle

ft. of Raised Or. Deck

ft. Moulded Depth

ft. ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No.

3726

Port

Ch

Classed

0.0 ft. No. 1. 07

100A1

7.88

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Upper deck flat. in completion of survey held in London as intimated by letter from Mr J.H. Smith dated 23<sup>rd</sup> June.

Now done:— The iron flat of upper deck scaled, examined repainted.

## PRESENT CONDITION OF THE

Decks	good	Plank (Bottom) & Counter	good	Ceiling		Boats	
Waterways	✓	Treenails or Rivets	✓	Rudder	✓	Masts, Yards, &c.	
Comings	✓	Breasthooks and Stemson		Windlass & Capstan		Condition, how ascertained	
Up'r Dk. Beams & Fastenings	✓	Transoms, Pointers, & Crutches		Pumps		Sails	
Low'r Dk. Beams & Fastenings	✓	Timbers of Frame at the opening	✓	Cement (if Iron Ship)		Anchors No. of	
Planksheers	✓	Ditto ditto at other places		Caulking of Bot'm, D'k, & Wat'ways		Cables	
Sheerstrakes	✓	Keelsons		Copper, or Y.M. (State if on Felt.)		Hawsers & Warps	
Topsides	✓	Clamps & Shelves		When put on		Standing & Running Rigging	
Wales	✓						
Engine Room Skylights	✓	Coal Bunker, Openings, Lids, &c.	good	Scuppers	—	Cargo & Main Hatchways	
						Hatches	

General Observations, Opinion as to Class, Recommendation, &c.:

The upper deck flat has been scaled, in completion of survey held in London and is now in good condition

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:
Survey Fee (per Section 28) .....	£	:	:
Special on Damage, Fee (if any) (per Sec. 28)....	£	:	:
*Certificate (if required) to be sent as per margin	£	:	:
Travelling Expenses (if chargeable) .....	£	:	:
Second Surveyor's Fee (if any) .....	£	:	:

Fees applied for,

18

Received by me,

18

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned:

RS 6/90

FRI 4 JULY 1890

100A1

on Low Rep

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.

GLS160-0114

State if a Report is also sent on the Machinery of the Ship. Yes

\* Certificate to be sent to

[Form No. 2 for Repairs—10000—13 8/99—Transfer Ink.—T & S.]  
The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.