

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

AUG 14 1896

Date of writing Report 10th August 1896 When handed in at Local Office 10th August 1896 Port of Glasgow

No. in Reg. Book. Survey held at Glasgow Date, First Survey 7/187 Last Survey 1896

410 on the Machinery of the Wood, Iron or Steel S Scotsman Master J W Bice

Tonnage { Gross 181 Net 70 Vessel built at Irvine By whom J H Gilmore When 1894

Registered Horse Power 25 Engines made at Glasgow When 1894 Boilers, when made (Main) 1894 (Donkey) None

No. of Main Boilers 1 Owners Kennedy & Son Port Glasgow Voyage Coasting

No. of Donkey Boilers None Steam Pressure in Main Boilers 120 If Surveyed Afloat or in Dry Dock Slipway (State name of Dock.) Hellinough

Last Survey No. 187 Port Glasgow

Particulars of Examination and Repairs (if any) Docking

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

CHARACTER for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned to special survey.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>100 A 1</u> <u>4-95</u>		<u>L M C</u> <u>7-94</u>

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.

Do. " Donkey " " No.

If this was not done, state for what reasons? Not due for survey.

And what parts of the Boilers could not be thus thoroughly examined? -

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -

Did the Surveyor examine the Safety Valves of the Main Boiler? -

At what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine the Safety Valves of Donkey Boiler? -

To what pressure were they afterwards adjusted? -

Has the propeller shaft been drawn and examined at this time? No

If the Survey is not complete state what arrangements have been made for its completion? Complete.

When this vessel was on slipway the propeller and sea cock fastenings were examined & found to be in good condition.

## General Observations, Opinion, and Recommendation:—

The machinery of this vessel so far as seen, is in good condition and is eligible in my opinion to remain as classed in register book without fresh record of survey.

	£	s	d	Fees applied for
Office or Registration Fee (per Sec. 27)				18
Survey Fee (per Section 28)				
Special Damage Fee (per Section 28)				
Travelling Expenses (if chargeable)				18

George Murdoch  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required. Committee's Minute TUES, AUG 18 1896 Assigned as now



665175-0262

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

14608  
It is submitted that  
this vessel is eligible to  
remain AS CLASSED.

17-8-96  
J. H. [Signature]

*Report of Survey for Repairs, etc., of Engines and Boilers.*

*Particulars of Examination Report (if any) See Copy*

*100 A 1*

*17-8-96*

*14608*

*It is submitted that this vessel is eligible to remain AS CLASSED.*

*J. H. [Signature]*

*17-8-96*

*14608*

*Report of Survey for Repairs, etc., of Engines and Boilers.*

*Particulars of Examination Report (if any) See Copy*

*100 A 1*

*17-8-96*

*14608*

*It is submitted that this vessel is eligible to remain AS CLASSED.*

*J. H. [Signature]*

*17-8-96*

*14608*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019  
Lloyd's Register  
Foundation