

S. S. Vascongada Glasgow Report No. 8165
 LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING
 No. 4486 (Received in London Office)



TESTS OF BOILER STEEL.

Tests of 4 Steel Plates manufactured by Messrs The Clydesdale Iron & Steel Co of Mossend
 for Boiler No. 305 to be constructed by Messrs A. Stephen & Sons of Glasgow
 for their S.S. No. 305

Date first visit _____ last visit April 27th 1887. No. of visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ samples as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
											The other plates in this batch with the tensile test were reported April 16 th 1887 Report No. 4661

199
5/6/87

Fee £ : :
 Expenses £ : :
 £ : : _____

To be paid by _____

© 2021
 H. M. Dove
 Surveyor, Lloyd's Register,
 Glasgow