

- 1st. On the several parts of the frame, when in place, and before the plating was wrought }
2nd. On the plating during the process of riveting

*Specially Surveyed 1882: - May 2. 15. 22. 30;
June 5. 7. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30.*

GRK300 - 0015

REPORT, No.

8401

FROM

Greenock

DATE

3/5/83

ON THE

Barrington

REMARKS OF THE CHIEF SURVEYOR.

*It is submitted that this vessel appears worthy
of the favorable consideration of the Committee
to be classed 100 A "Steel" as contemplated*

20 Kts "Steel"

3 Kts Beams.

*To render the vessel eligible for the Figure,
a stream chain should be supplied or an additional
hawser to conform with the requirements of Table 22*

© 2019

Lloyd's Register

Foundation