

Net Tonnage 586.00
Gross Tonnage 53.55

1st Number

Length on deck from after part of stem to fore part of } 258.5

Owners George

F.E.

Received by Chief Surveyor 18.7.98

Received from Chief Surveyor

VESSEL'S NAME Ste. S.S. "Denevell"

Report Euk No. 12114

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

| Items. | Additions (if any) required by Rules, or as approved. | On account of:— |
|----------------------|---|-----------------|
| Main Sheerstrake . . | 2/20" | Proportions |
| Spar Sheerstrake . . | / | / |

Description of Framing:— Deep framing.
(viz., ordinary, deep, zed, channel or bulb-angle).

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed † 100 A 1 ("Steel") as recommended.

† 100 A 1 ("Steel")

1 TR (Stl) + deep framing

W. B = Cee DBa 82' f96' 3596 APT 23E.

FK 4BH Cam. LA & CP.

C.H.J.
18/7/98



© 2019

Lloyd's Register Foundation

ARK 411-0075

| Part | Material | Thickness | Remarks |
|-------------------------------|----------|-----------|---------|
| Quarter, 'tween Dks., in Hold | | | |
| Forecastle Deck | | | |
| Angle on ditto | | | |
| Tie Plates | | | |