

ANNUAL SURVEYS.

Rev 22/2/92

No. 1029 Survey held at Grangea Date 2nd to 14th Febr. 18 72
 262 on the Iron 18th "Jessie Jamieson" Master Outerbridge
 Tonnage 504 Built at Pallion When built 1863
 By whom built Osswald Owners Hargrove & Co.
 Port belonging to Liverpool Destined Voyage Chile
 If Surveyed Afloat or in Dry Dock On Patent Slip

Last Survey, No. 6260 Port of Iron Classed *A\ SS. No. 1 68
10-71

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places <u>Good</u>	Sails
Planksheers	Keelsons	Anchors No. of <u>3 1/2 15 2K</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where examined

*This Vessel has been cleaned on the outside coated, is now in good condition in my opinion eligible to be continued as classed *A.I.*

Committee's Minute 23rd February 1872

Character assigned

*A I

W. M. Johnson

Special £1-1-0 Feb 1872

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18 ____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18 ____

Character assigned _____



© 2019

Lloyd's Register

Certificate (if required).

120450-0296