

# ANNUAL SURVEYS.

No. 26049 Survey held at Liverpool Date, first Survey May 9<sup>th</sup> Last Survey May 27<sup>th</sup> 1878.  
 No. in Reg. Book. 275 on the Ship "Bengal" Master H. Irving.  
 Tonnage 1296 Built at Liverpool When built 1868 - 7 mo.  
 By whom built Clover Owners E. F. Powell & Co  
 Port belonging to Liverpool Destined Voyage Calcutta.  
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Last Survey, No. 18559 Port of Iron Classified Good S.S. Liv No. 2.77. 677.  
 Present Condition of the Decks Good  
 Waterways "  
 Comings "  
 Upper Deck Beams & Fastenings "  
 Lower Deck Beams & Fastenings "  
 Planksheers "  
 Sheerstrakes "  
 Topsides "  
 Wales "  
 Plank (Bottom) and Counter "  
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool May 28<sup>th</sup> 1878 J. Shilston  
 Character assigned \*A1. Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) 75 Paid 28/5 1878 J. F. L.

No. 197 Survey held at Liverpool Date, first Survey May 13<sup>th</sup> Last Survey May 15<sup>th</sup> 1878.  
 No. in Reg. Book. 197 on the Bark "Santa Rosa" Master J. Archer  
 Tonnage 568 Built at Liverpool When built 1862 - 7 mo.  
 By whom built Vernon Owners Hope Bros.  
 Port belonging to Liverpool Destined Voyage Valparaiso.  
 If Surveyed Afloat or in Dry Dock Gt. Float Dry Dock.

Last Survey, No. 18953 Port of Iron Classified Good S.S. Lon No. 3.75. 677.  
 Present Condition of the Decks Good  
 Waterways "  
 Comings "  
 Upper Deck Beams & Fastenings "  
 Lower Deck Beams & Fastenings "  
 Planksheers "  
 Sheerstrakes "  
 Topsides "  
 Wales "  
 Plank (Bottom) and Counter "  
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool May 28<sup>th</sup> 1878 J. Shilston.  
 Character assigned \*A1. Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) 75 Paid 28/5 1878 J. F. L.

IRON 478-0020



Bengal  
Santa Rosa

26049



© 2019

Lloyd's Register  
Foundation