

# ANNUAL SURVEYS.

24125  
Rev 31/7/19 11.20

No. 4926 Survey held at Glasgow Date, first Survey 5<sup>th</sup> June Last Survey 1<sup>st</sup> July 1879  
 No. in on the S. Loch Fife Master Wm Stewart  
 Reg. Book. 599 Tonnage 1235 Built at Glasgow When built 1877-11 mo.  
 By whom built A & S. Inglis Owners General Shipping Co.  
 Port belonging to Glasgow Destined Voyage Adelaide S.A.  
 If Surveyed Afloat or in Dry Dock On Pointhouse Slip and Afloat

Last Survey, No. 19892 Port of Iron Classed 100A1 12/77  
 Present Condition of the  
 Decks Good Rivets Good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do ~~Transoms~~ of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do ~~Transoms~~ ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shelves Securities do  
 Topsides do Ceiling do  
 Wales do Rudder do  
~~Plating~~ (Bottom) and Counter do Copper or Y.M. Coating When put on 1879  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. —

12 Bulwark stantions removed repaired and re-fastened. Cement in gutter waterway made good. Bottom re-coated

Committee's Minute 1st August, 18 79. Saml Laphorn  
 Character assigned 100A1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18 —

No. 4926 Survey held at Glasgow Date, first Survey 9 July Last Survey 16<sup>th</sup> July 1879  
 No. in on the S. S. "North Eastern" Master W. Kinnear  
 Reg. Book. 357 Tonnage 358 Built at Glasgow When built 1877-6 mo.  
 By whom built Inglis Owners Ardrossan Shipping Co.  
 Port belonging to Ardrossan Destined Voyage Ardrossan and Belfast  
 If Surveyed Afloat or in Dry Dock On Pointhouse Slip and Afloat

Last Survey, No. 22964 Port of Iron Classed 100A1 10/78  
 Present Condition of the  
 Decks Good Rivets Good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do ~~Transoms~~ of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do ~~Transoms~~ ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shelves Securities do  
 Topsides do Ceiling do  
 Wales do Rudder do  
~~Plating~~ (Bottom) and Counter do ~~Copper or Y.M.~~ Coating When put on July 1879  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. —

Bottom cleaned examined and re-coated - Propeller renewed - Thrust shaft found defective renewed (per Engineer Surveyors Report)

Committee's Minute 1st August, 18 79. Saml Laphorn  
 Character assigned 100A1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18 —