

ANNUAL SURVEYS. 28742

No. 29849 Survey held at London Date, first Survey 24th Nov Last Survey 24th Nov 1880
 No. in on the Iron S.S. "Fanny" Master Owen
 Reg. Book. 85 Tonnage 92.308.258 Built at Glasgow When built 1878-3mo
 By whom built Inglis Owners J. Burnett & Sons
 Port belonging to London Destined Voyage Rouen
 If Surveyed Afloat or in Dry Dock Mountainudson

Last Survey, No. 23392 Port of Iron Classed 100A1
 Present Condition of the Decks Good Treenails Rock Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Cement When put on 1878
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. 5 planks of Deck renewed with Yellow Pine. Bottom
recoated. She is now in good condition and in my opinion
eligible to continue as Classed

Committee's Minute Tuesday, December, 14th 1880.
 Character assigned 100A1 JBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Present Condition of the Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

IRON 47-0316