

ANNUAL SURVEYS.

3180

No. 3100 Survey held at London Date Feb 28th 1837
 on the Brig Ester Master Haywood?
 Tonnage 265 Built at Afld When built 1810
 By whom built _____ Owners Robinson & Co
 Port belonging to London Destined Voyage Afld
 If surveyed Afloat or in Dry Dock Mr. Curling & Co. Wagon

Original Survey, No. 13 Port of Poole Classed A1
No 2177 " London

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time, caulked from the Copper up - has caulked
 as required by the Instructions, will be firmly aloft
George Bayley

Committee Minute 7 March 1837
 Character assigned 12 A 1
LB

Resurvey

No. 353 Survey held at London Date February 28 1837
 on the Schooner London Packet Master Lighton
 Tonnage 32 Built at Glasgow When built 1837
 By whom built Beddewick Owners Shaw & Co
 Port belonging to Glasgow Destined Voyage Glasgow
 If Surveyed Afloat or in Dry Dock Dundee Wharf

Original Survey, No. 353 Port of Glasgow 1837 Classed 11 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, The Floors are sided 8 x 8 ft. Top timbers 6.5 ft x 5 with a round face of 18 in chis which
 as required by the Instructions, appears to be quite as much as can be allowed for scantling of such dimensions -
The Floors are well squared but not quite free from sap - The Top timbers are
quite square & free from sap - The workman and his throughout appears to be very good
the bolts and through fastenings of good size & sufficient in number - She is in
my opinion entitled to 11 A but does not in my estimation quite come up to the
standard for 12 A 1
George Bayley
 Committee Minute 2 March 1837

Character assigned 12 A 1
LB