

ANNUAL SURVEYS.

9465

No. 94 Survey held at London Date Feb 2nd 1843
 on the Brig Harmony Master Pathe
 Tonnage 245 Built at Sunderland When built 1840
 By whom built _____ Owners Crowder & Co.
 Port belonging to London Destined Voyage Collier
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1768 Port of Sunderland, Lon 8168. Classed 7 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>not seen</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>Good & sufficient</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion,
 as required by the Instructions,

*This vessel is in a very efficient state
 & may remain as classed*

Committee Minute 21st February 1843

Character assigned 7 A 1

No. 385 Survey held at London Date Feb 13th 1843
 on the Brig Alexander Johnston Master Swan
 Tonnage 29 1/2 Built at Dumbarton When built 1835
 By whom built _____ Owners W. Laid
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1441 Port of Clyde, Lon 5886, Brs 546 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good when seen</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Masts, Yards, &c. <u>New main & Mizzen masts</u>
Spirkettling <u>"</u>	Wales <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Cables <u>Good & sufficient</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Breasthooks <u>"</u>	Windlass <u>"</u>	Copper <u>Repaired</u>

General Observations and Opinion,
 as required by the Instructions,

*This ship is in good condition & may remain
 as classed*

Committee Minute 21st February 1843

Character assigned 12 A 1



© 2019

Lloyd's Register
 Foundation

Lon 5886-0122