

ANNUAL SURVEYS.

10,129

LL

No. 909

Survey held at Londond

Date Sept 27th 1843

On the Br Sydney

Master Porter

Tonnage 310

Built at Glasgow

When built 1840

By whom built

Owners 27

Port belonging to Glasgow

Destined Voyage Wellington

If Surveyed Afloat or in Dry Dock Cairlie's Dock

Original Survey, No. 832 Port of Glyde 1840 Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>do</u>	Pumps <u>Good Efficient</u>
Lower Deck Beams & Fastenings <u>shifted</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>Trimmed out</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>Efficient</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>Good</u>
Breasthooks <u>do</u>	Rudder <u>do</u>	Copper <u>Efficient</u>
	Windlass <u>do</u>	

General Observations and Opinion, At the present time stripped off wood and copper sheathing
as required by the Instructions, Carried from the keel up - upper course
apparent over all - Sheathed with yellow
Copper as before - In my opinion she is eligible to
remain as classed 10 A 1

Committee Minute 17th October 1843

Character assigned 10 A 1 Record Ym
LL

© 2019
George Dingley
Hull's Register
Foundation

2110616-0113