

# ANNUAL SURVEYS.

11530  
16.5.1845

No. 215 Survey held at London Date May 24<sup>th</sup> 1845  
 on the Ship "Benjamin Greene" Master Law  
 Tonnage 318 Built at Sunderland When built 1838  
 By whom built 405 Owners Greene & Son  
 Port belonging to London Destined Voyage West Indies  
 If Surveyed Afloat or in Dry Dock Keeps Dry Dock

Last Survey, No. 10A1 Port of London Classed 10A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>do</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions,

Had ground on her last voyage but sustained no damage beyond the forcing off part of false keel now with few sheets of yellow metal made good is in an efficient condition and may remain as classed Four tons

Committee Minute 16th May 1845

Character assigned

Special Damage £2.2

No. 215 Survey held at London Date 21 April 1845  
 on the Ship "Hebrides" Master Melville  
 Tonnage 572 Built at Greenock When built 1841  
 By whom built 646 Owners Dennistoun  
 Port belonging to Greenock Destined Voyage —  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 9803 Port of London Classed 10A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>do</u>	Pumps <u>efficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirketting <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u> (Outside to the Water's Edge.)	Anchors No. of <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>ed abroad 1844 224200L</u>

General Observations and Opinion,

as required by the Instructions,

Is in an efficient condition and may remain as classed - Had to have ground and shipped and reshipped at Singapore in the last year bottom then caulked

Committee Minute 16th May 1845

Character assigned

Special Valuation £5.5.0

