

ANNUAL SURVEYS.

12189

No. ✓ Survey held at Sunder Date Dec 7th 1846
 on the Ship Indian Master C C Sutherland
 Tonnage 475 Built at Glasgow When built 1834
 By whom built ✓ Owners Gemmell
 Port belonging to Glasgow Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

12189

Last Survey, No. 1078 Port of Chide

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame <u>Sound & secure</u>	Pumps <u>✓</u>
Lower Deck Beams & Fastenings <u>✓</u>	Top-sides <u>Good</u>	Masts, Yards, &c. <u>✓</u>
Spirkettling <u>Good</u>	Wales <u>✓</u>	Sails <u>Well found</u>
Plank Shears <u>✓</u>	Counter <u>✓</u>	Cables <u>✓</u>
Waterways <u>✓</u>	Plank and Treennails <u>✓</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Bower 18 lb. 2 Widge</u>
Hatchway Coverings <u>✓</u>	Rudder <u>✓</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>✓</u>	Windlass <u>✓</u>	Copper <u>1844</u>

General Observations and Opinion, Having been on shore coming down Canton River has had the Ropes
 as required by the Instructions, chipped off the heel & two sheets aboat, being in shams, keel beam
and two aboat caulked & ropes replaced as before and is in all
other respects fit to return her present ship.

Committee Minute 13th Jan'y 1846

Character assigned 12 A 1

No. ✓ Survey held at Sunder Date January 9th 1846
 on the Ship Barbara Gardner Master A. Beecher
 Tonnage 330 Built at Sunderland When built 1836
 By whom built ✓ Owners Gordon
 Port belonging to Sunder Destined Voyage Coburg
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 11124 Port of Sunder

Classed 11 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame <u>Sound & secure</u>	Pumps <u>✓</u>
Lower Deck Beams & Fastenings <u>✓</u>	Top-sides <u>Good</u>	Masts, Yards, &c. <u>✓</u>
Spirkettling <u>Good</u>	Wales <u>✓</u>	Sails <u>Well found</u>
Plank Shears <u>✓</u>	Counter <u>✓</u>	Cables <u>✓</u>
Waterways <u>✓</u>	Plank and Treennails <u>✓</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Bower 18 lb. 2 Widge</u>
Hatchway Coverings <u>Good</u>	Rudder <u>✓</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>✓</u>	Windlass <u>✓</u>	Copper <u>1844</u>

General Observations and Opinion, From her general condition and appearance I am of
 as required by the Instructions, opinion she may retain her present ship.

Committee Minute 13th Jan'y 1846

Character assigned 11 A 1

© 2019
 Lloyd's Register
 Foundation

LON 620-0224