

ANNUAL SURVEYS.

13509
no. 103

No. 312 Survey held at London Date 9 June 1847
 on the St. Raphael Master Morrison
 Tonnage 412 Built at Glasgow When built 1825
 By whom built 538 Owners Potter & Co
 Port belonging to Glasgow Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock in M. Carter's Dock

Last Survey, No. 12583 Port of London Classed 10A1

The present Condition of the		
Decks <u>Prop deck Culked</u>	Trenails <u>apparently Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Culked Good</u>	Breasthooks and Stenon	Pumps
Cowings	Transoms, Pointers, and Crutches	Boats <u>three</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchor No. of <u>3 1 1</u>
Sheerstrakes	Ceiling	Cables <u>suff</u>
Topides <u>Culked down</u>	Rudder	Hawsers and Warps <u>in</u>
Wales	<u>Copper & Metal new on</u>	Standing & Running Rigging <u>D</u>
Plank (Bottom) and Counter	<u>paper June 1847</u>	

General Observations and Opinion,
*at present bottom stripped Culked and
 Coppered with yellow Metal on felt. Is in
 most efficient Condition and may remain
 15th July 1847*

Committee Minute 15th July 1847

Character assigned 10 A 1 as Classed 10A1
by

Certificate (if required)

No. 262 Survey held at London Date 11 June 1847
 on the "St. Waterlily" Master Kant
 Tonnage 262 Built at Southampton When built 1824
 By whom built 1 Owners J Dawson
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock in Sawmiller Dock

Last Survey, No. 12194 Port of London Classed 10A1

The present Condition of the		
Decks	Trenails	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stenon	Pumps <u>new belt pumps</u>
Cowings	Transoms, Pointers, and Crutches	Boats <u>three</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>suff</u>
Lower Deck Beams & Fastenings	Keelsons <u>Good</u>	Sails
Planksheers <u>Good</u>	Clamps and Shelves	Anchor No. of <u>3 1 1</u>
Sheerstrakes	Ceiling	Cables
Topides	Rudder	Hawsers and Warps
Wales	<u>Copper</u>	Standing & Running Rigging <u>in</u>
Plank (Bottom) and Counter	<u>new on felt</u>	

General Observations and Opinion,
*at present bottom stripped Culked new in
 shores and bottom is coppered on felt. old boat top
 of 1847 remains on - the short fellies under felt
 of 1847 remains on - the short fellies under felt*

Committee Minute 15th July 1847

Character assigned 10 A 1 as Classed 10A1
by

Certificate (if required)

LON 223-0133