

ANNUAL SURVEYS.

1389

No. 808 Survey held at London Date December 1847
 on the Rt Sydney Master White
 Tonnage 310 Built at Glasgow When built 1840
 By whom built _____ Owners W J Kidson
 Port belonging to Glasgow Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Fletcher's Dock

Last Survey, No. 12881 Port of London Classed AA1

The present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>"</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion. Bottom examined and appears in all respects in a good condition to retain her present shape

Committee Minute 14th Decr 1847

Character assigned AA1

Certificate (if required)

No. 894 Survey held at London Date December 1847
 on the Mount Stuart Elphinstone Master Hutton
 Tonnage 611 Built at Bombay When built 1826
 By whom built _____ Owners J & J Thomas
 Port belonging to London Destined Voyage Gibraltar & Robert Town
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 12744 Port of London Classed A. Historic

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & well seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers <u>good</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>4 Bower 1 Stn 2 Hdgro</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>"</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>good</u>		

General Observations and Opinion. Has been in dry dock, bottom examined & caulked from the Copper to the waterway beam, from her general good & efficient condition am of opinion she is fit for the safe conveyance of dry & perishable cargoes & from all parts of the world may retain her present shape

Committee Minute 14th Decr 1847

Character assigned AA1

Certificate (if required)