

# REPORT of SURVEY for REPAIRS.

*Change of owners*

1999

*Surveyed on*

No. 691 on the Ship "Strathfieldsaye" Master J. Brown  
 Survey held at London Date Oct<sup>r</sup> 19<sup>th</sup> 1855  
 Tonnage 554 Built at Sunderland When built 1852  
 By whom built Wm Connal Jun<sup>r</sup> Owners Wm Connal Jun<sup>r</sup>  
 Port belonging to Glasgow London Destined Voyage Myat  
 If Surveyed Afloat or in Dry Dock Nelson dry docks

st Survey, No. 17800 Port London Classed 10 A1.

PAIRS *Now done, the vessel caulked from keel to metal line and sheathed with yellow metal and felt.*

## Present Condition of the

Decks <u>good</u>	Treenails	Windlass and Capstan <u>good</u>
Waterways <u>good</u>	Breasthooks and Stemson	Pumps <u>good</u>
Comings <u>good</u>	Transoms, Pointers, and Crutches	Boats <u>3 good</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>good, yards new</u>
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons <u>where seen</u>	Sails <u>2 1/2 good suits</u>
Planksheers <u>caulked</u>	Clamps and Shelves <u>seen</u>	Anchors No. of <u>3 B. 18. 16</u>
Sheerstrakes <u>caulked</u>	Ceiling	Cables <u>good and sufficient</u>
Topsides <u>caulked</u>	Rudder	Hawsers and Warps <u>good &amp; sufficient</u>
Wales <u>caulked</u>	<u>yellow metal</u> When put on <u>now done</u>	Standing & Running Rigging <u>refitted</u>
Plank (Bottom) and Counter <u>caulked</u>	<u>Copper on felt</u>	

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good

*This vessel is now in good and efficient condition and in my opinion eligible to remain as Classed 10 A1.*

*J. P. Light*

The Amount of Fee.....£ / : : is received by me,

Special..... : : }

Certificate (if required) : : - }

Committee's Minute 2<sup>nd</sup> November 1855

Character assigned 10 A1



© 2019

Lloyd's Register Foundation

LON636-0288