

# ANNUAL SURVEYS.

23028

No. 113 Survey held at London Date 19<sup>th</sup> December 1860  
 on the Ship Isabella Harris Master J. Mitchell  
 Tonnage 369 Built at Adrosant When built 1847  
 By whom built                      Owners J. Holmes  
 Port belonging to London Destined Voyage London to Kinsachie  
 If Surveyed Afloat or in Dry Dock St. Katharine's Dock

Nov 19. 12. 60

Last Survey, No. 22420 Port of London Classed 13A1

3/5-9

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>on belt</u> When put on <u>1859</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

*This ship had received the greater part of her cargo when she was left for survey. She appears in good and efficient condition, eligible to remain as classed until the reprinting of the registry book in June 1861*

Committee's Minute

21<sup>st</sup> December 1860

Character assigned

13A1

*MT*

*A. J. Munford*

Certificate (if required)

No.              Survey held at              Date              18              
 on the              Master               
 Tonnage              Built at              When built               
 By whom built              Owners               
 Port belonging to              Destined Voyage               
 If Surveyed Afloat or in Dry Dock             

Last Survey, No.              Port of              Classed             

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>            </u> When put on <u>            </u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways             

Committee's Minute              18            

Character assigned             



© 2019

Certificate (if required).

Lloyd's Register Foundation

LON 643-0374