

25343

REPORT of SURVEY for REPAIRS.Rev 2 of 3/63
C.M.

No. 3 Survey held at London Date March 21st 18 63
 on the BK "Kerelaw" Master P. Sasson
 Tonnage 325 Built at Ardrossan When built 1848
342
 By whom built Barr & Shearer Owners Whannell
 Port belonging to Arbroath Destined Voyage Demarara
 If Surveyed Afloat or in Dry Dock in globe & West India Docks

Last Survey, No. 1,468 Port Greenock Classed A1 in Red
5.62

REPAIRS

Stripped Yellow metal sheathing caulked from keel to metal line and
 re-sheathed with Yellow metal over felt.

Present Condition of the

Decks <u>Good</u>	Treenails <u>where seen</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>✓</u>	Breasthooks and Stemson <u>✓</u>	Pumps <u>✓</u>
Comings <u>✓</u>	Transoms, Pointers, and Crutches <u>✓</u>	Boats <u>✓</u>
Upper Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame <u>where seen</u> <u>✓</u>	Masts, Yards, &c. <u>✓</u>
Lower Deck Beams & Fastenings <u>✓</u>	Keelsons <u>not seen</u> <u>✓</u>	Sails <u>✓</u>
Planksheers <u>✓</u>	Clamps and Shelves <u>where seen</u> <u>✓</u>	Anchors No. of <u>3 B, 1 S, 1 K</u>
Sheerstrakes <u>✓</u>	Ceiling <u>✓</u>	Cables <u>✓</u>
Topsides <u>✓</u>	Rudder <u>✓</u>	Hawsers and Warps <u>✓</u>
Wales <u>✓</u>	Copper <u>F & Y M</u> When put on <u>1863</u>	Standing & Running Rigging <u>✓</u>
Plank (Bottom) and Counter <u>✓</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

Is now in good and efficient condition fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world and is in our opinion fit to remain as classed

The Amount of Fee.....£ 1 : — : — is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : 5 : —

Committee's Minute 10th April 18 63

Character assigned in red
rudder yell



© 2021

Lloyd's Register
 Foundation
 LON647-0049

Keruan



© 2021

Lloyd's Register
Foundation