

ANNUAL SURVEYS.

25587

Rev 27/7/63

No. 114 Survey held at London Date 27th July 1863
 on the Ship "Eraminondas" Master A. Heasley
 Tonnage 1125 Built at Quebec When built 1850
 By whom built Liverpool Owners Messrs Granger & Co
 Port belonging to Belfast Destined Voyage Aden
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 17534 Port of Liverpool. Classed Red A1
SS 62-5 ms SS 62-4 ms 4-62
See 62 See 60

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>YM</u> When put on <u>1862</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

Good where seen

Good where seen

Good and efficient

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

She is now in good condition, and fit in our opinion for the safe conveyance of dry and perishable goods, to and from all parts of the world and to remain as

Committee's Minute 28th July 1863 Classed Red A1 - 4 years
 Character assigned A in red WM
B. W. Wymouth
Harry Cornish
 Certificate (if required)

No. 358 Survey held at London Date July 7th 1863
 on the Ship "John Bright" Master S. Cole
 Tonnage 541 Built at Dumbarton When built 1847
 By whom built Gurnsey Owners Carre & Co
 Port belonging to Gurnsey Destined Voyage not fixed
 If Surveyed Afloat or in Dry Dock Messrs Young's Dry Dock

Last Survey, No. *2553 Port of Bristol. Classed 12 A1 Test 62
62 8 years

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

Good where seen

Good where seen

Good and efficient construction

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Now done. Metal sheathing painted - She is now in good condition and fit in our opinion for the safe conveyance of dry and perishable goods, to and from all parts of the world and to remain as

Committee's Minute 28th July 1863 and to remain as Classed 8 A1
 Character assigned Best 8 A1 WM
B. W. Wymouth
Harry Cornish
 Certificate (if required).