

ANNUAL SURVEYS.

25686

No. 14 Survey held at London Date Aug 14th 1863
 on the Ship "Harwich" Master G. Franklin
 Tonnage 613 Built at Harwich When built 1837
 By whom built _____ Owners Messrs Bonnis & Co
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock Union Day Dock & London Dock

Last Survey, No. 24883 Port of London Classed G.A. 1.
8, 62

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Omings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>Good</u>	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves } <u>Good where seen</u>	Cables
Oppsides } <u>Caulked</u>	Ceiling	Hawsers and Warps
Vales	Budder	Standing & Running Rigging
Plank (Bottom) and Counter } <u>Good</u>	<u>Yellow Metal</u> When put on <u>1862</u>	<u>Refitted</u>

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where tested
Now done, Caulked from the Metal Sheathing to the Gunwale - her Metal Sheathing Datches - She is now fit in my opinion to remain as classed G.A. 1.

Committee's Minute 11 September 1863

Character assigned G.A. 1

Certificate (if required)

No. _____ Survey held at London Date July 7th 1863
 on the Barge "John Bright" Master J. Cole
 Tonnage 520 Built at Dumbarton When built 1847
 By whom built _____ Owners Messrs Carr & Co
 Port belonging to Guernsey Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Messrs Gumps Dry Dock

Last Survey, No. _____ Port of _____ Classed Dist 62 - 83rd A. 1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Omings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>Good</u>	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves } <u>Good where seen</u>	Cables
Oppsides } <u>Good where seen</u>	Ceiling	Hawsers and Warps
Vales	Budder	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Yellow Metal</u> When put on <u>1862</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen
Now done, her Metal Sheathing Painted - She is now fit in my opinion to remain as classed G.A. 1.

Committee's Minute _____ 18

Character assigned _____

Certificate (if required)