

25692

REPORT of SURVEY for REPAIRS.

No. 220
on the

Survey held at

London

Date

Sept 1st 1863

13th "Akbar"

Master

D Fraser

Tonnage

318
337

Built at

Greenock

When built

1839

By whom built

Owners

Messrs Baird & Co

Port belonging to

Glasgow

Destined Voyage

Madras

If Surveyed Afloat or in Dry Dock

Bull Head Dry Dock

Last Survey, No.

1814

Port

Glasgow

Classed

11 A 1

Net 57 - 8 -

REPAIRS

Now done, Bottom caulked
and Sheathed with Yellow Metal
on Felt

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

She is now in good condition and in my
opinion fit for the conveyance of dry and
perishable goods, to and from all parts of
the world and to remain as classed A 1

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 18th September 1863

Character assigned

Rest 8 1/2

record 111

83

Charge £1-1



© 2021

Lloyd's Register
Foundation
LON647-0361