



COPY.

Lloyd's Register of Shipping.

By-whom 15 FEB 1949
 Henty & Son Ltd.
 (Donkey)
 Address
 Port Sydney N.S.W.
 Particulars of Classification as in Register

Port SYDNEY, N.S.W.

24th January, 1949.

100	A1
7,48	
SS.Syd. 7,47	
Cargo Data	

This is to Certify that I have

Surveyed the S.S. "BOMBO" - of Sydney, N.S.W.

540 Gross Registered Tons,

for examination in dry dock and repairs to hull damage,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be continued as classed, with record of Docking Survey 1,49 made in the Register Book,

being fit to carry dry and perishable cargo.


(See endorsement on back hereof)

(SGD) H. GERRARD.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B.) 15M-9/21-J. & O'S. (PRINTED IN AUSTRALIA)



Survey Fee (per Section 29) £ : : :
 Special Damage or Repair Fee (if any) £ : : :
 Fees applied for, 19

...ed to Rule requirement and found sound and tight. Shoe plate at aft
cropped and renewed for a length of 14 feet

18 FEB 1949

FOR LONDON COPY.

Lloyd's Register of Shipping

Indented shell plates D. 2 & E. 2, port side, with frames and stringer in way, to be dealt with at Owners' convenience.

SYDNEY, N.S.W.

Port

Said January, 1949.



This is to Certify that I have

Surveyed the "S.S. 'ROMA'" of Sydney, N.S.W.

240 Gross Registered Tons,

for examination in my dock and repairs to hull repairs

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be continued as classed,

with record of Docking Survey 1, 49 made in the Register

Book.

dry and perishable cargo.


being fit to carry

(See endorsement on back hereof)

(SGD) H. GERRARD.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Date
No
Reg.
532
Tonn
Nor
Horse
No. of
No. of
Steam
in M
in D
Last
Part
(Perio
cause
acco
besid
dates
In dam
Was a d
Did the
" "
If this w
And wha
Also wha
Surveyor
State late
Did the S
Has screw
Has shaft
Has the sh
State date
Engin
If so, did th
Has the ins
If the Surv
The
condit
General C
(State cl
alter
L
Survey Fee (p
Special Dam