

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME *Stl. T. S. Motor Vessel "Ediba"* Report *Gls.* No. *42668.***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey \_\_\_\_\_ When due \_\_\_\_\_

✱ 100.A.1. (Steel) "Shelter Dk. with Freeboard."  
 2 Dks (Stl) & Shelter Dk (Stl-pt. ws)  
 Cell DB 338'1005t, Tank between tunnels 55t, FPT 116t, APT 123t.  
 FK, 7BH (6BH to Shelter Dk), pt. Cem. Lloyds A+CP,  
 P43', B151', F48' on Shelter Dk.



*A.W.J.*  
 © 2015 *25/4/23.*

Lloyd's Register  
 Foundation

W103-0200